

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No 128179

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080199-4

RECEIVED FROM

DATE REC'D 1-22-57

P. O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO. 322	DRAWING NUMBER 000000	DWG. DASH OR STANDARD PART NO. 10000	DWG. REV. 0	LOT NO. 0	CLASS NUMBER 00	OPER NUMBER 00	BUY OUT CODE NO. 0	ACCT. OR W. O. NO. 0
QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION						QUANTITY	REMARKS	
	738245 BRKT ASSY SWITCH ADJUST 1 N/P						2		
	SHIP MEMO 35866								
RECEIVED BY	INSPECTED BY	DATE 1/22/57				REJECTS RETURNED ON SHIP MEMO NO.			

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA 8, CALIF.

No 128180

RECEIVED FROM

DATE REC'D 1-22-57

P. O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO	CONTRACT CODE NO. 322	DRAWING NUMBER 000000	DWG. DASH OR STANDARD PART NO. 20050	DWG. REV. 0	LOT NO. 0	CLASS NUMBER 10	OPER NUMBER 00	BUY OUT CODE NO. 0	ACCT. OR W. O. NO. 0
QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION						QUANTITY	REMARKS	
	732345 BEARING CAM BRACKET						10		
	SHIP MEMO 35869								
RECEIVED BY	INSPECTED BY	DATE 1/22/57				REJECTS RETURNED ON SHIP MEMO NO.			

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080199-4